
X-labs minutes 3-4

Written by Billie Taylor

Friday, 04 March 2011 17:24 - Last Updated Friday, 04 March 2011 17:25



X-labs minutes 3-4

| Written by Billie Taylor Friday, 04 March 2011 17:24 - Last Updated Friday, 04 March 2011 17:25 |
|--|
| UAV will release and fly home |
| Will need to be metal to survive the speeds |
| Use a parachute until below the Jet Stream and then deploy engine to fly home |
| Buy an airframe and reinforce it with carbon fiber |
| What do we need |
| A large, stable airframe |
| Custom electronics |
| GPS 18 OEM receiver |
| Ardupilot |
| More to come! |
| |